

Guinness Property - Empty Homes - Handover Form

12 Kenwood Clo	ose, Kingswood,Bri	stol BS154TE			Incomplete
Score	0 / 8 (0%)	Flagged items	0	Actions	0
Address					
12 Kenwood C	lose, Kingswood,B	ristol BS154TE			
Works Order	Number				
Conducted or	ı				20.09.2023 15:28 UTC
Inspected By John Watchman			John Watchman		
First Inspecti	on Overall Rating				Poor

OFFICE USE ONLY	0 / 7 (0%)
DOCS SENT	
SOR VALUE MATCH	
VP DATES	
GRN PO'S	
ASSIGN SOR'S	
UPDATE WB	
PLANCAP DOCS	

Audit

NOTES

Access Details Whilst Property Void

Key safe at front door 1902

COMPONENTS

DECORATIONS	DI	EC	OR	AT	ΙΟ	NS
-------------	----	----	----	----	----	----

KITCHEN

Flooring to renew





BATHROOM

Bathroom wash hand basin needs renewing Re tile over bath



Photo 3













Photo 8

REAR DOOR



Photo 9

ALL WINDOWS



0/1(0%)



 \Box













Photo 11

Is the power on at Pre Inspection?

Photo 12

Phot

Photo 13

Photo 14

Photo 15



QUANTUM HEATER UPGRADE	
Damp & Mould in the property?	No
Electric Info	
Location of Consumer Unit	
In Hallway by front door	
Add Clear Photo	
Photo 17	
Electric Certificate Number	
Isolation Switch Fitted	Yes
Info;	
Type of Meter	Smart
Add Clear Photo Fhoto 18	
Is it an Economy 7 Meter?	Yes

Before Value (£)

After Value (£)

Serial Number

22MO153378

Property Of

Вg

Before Readings

06471

Meter in debt Green energy topping up

After Readings

Gas Info

Gas In Property? Yes	Gas In Property?		Yes
----------------------	------------------	--	-----

Location of Gas Meter

External front

Gas Cert Number

Type of Meter	Smart
---------------	-------

Add Clear Photo



Photo 19

Serial Number

22062335

Reading

00491.585

Before Value (£)

9.07 in debt

Green energy are topping up meter

After Value (£)

British Gas Portal Updated at Stage 1 & 2

Water Info

Location Of Stop Tap

Under kitchen sink



Water Meter Fitted?

Before Reading

08740.69

After Reading

Serial Number

Unable to read




Loft Info

General condition of loft		
Loft insulation present	Yes	
Thickness of insulation (recommended 250-270mm)	Inadequate	

Photo of Loft Space









BEFORE PHOTOS

Photo 27

Photo 33

Photo 39



Photo 26



Photo 32














Photo 51





Photo 28



Photo 34







Photo 53

Photo 29

Photo 35

Photo 41

Photo 47




Photo 48

Photo 54

Photo 30



Photo 36



Photo 31




Photo 37



Photo 43



Photo 49



AFTER PHOTOS

Number of Keys Returned

Communal door	0 From 0 to 10
Fob	0 From 0 to 10
Front Door	0 From 0 to 10
Rear Door(s)	0 From 0 to 10

Window Locks	0 From 0 to 10
Shed/Outbuilding	0 From 0 to 10
Gate Padlock	0 From 0 to 10
Meter Cupboard	0 From 0 to 10
Location Of Returned Access Key	

SIGN OFF

RETURNED

This property has been prepared to The Guinness Partnership Standard Re-Let charter by Guinness Property. It has been left in a clean state. Dust covers have been removed from smoke/heat detectors and are in good, working order.

OVERVIEW OF ANY DEFERRED WORKS

CUSTOMER'S GAS RECOMMISION INSTRUCTIONS

WORKS ORDER NUMBER;

Media summary








Photo 3



Photo 5



Photo 7



Photo 2



Photo 4





Photo 8



Photo 9



Photo 11



Photo 13





Photo 10



Photo 12



Photo 14



Photo 16



Photo 17



Photo 19







Photo 20



Photo 22







Photo 25



Photo 27



Photo 29





Photo 26



Photo 28



Photo 30



Photo 31



Photo 33



Photo 35



Photo 37



Photo 32



Photo 34



Photo 36



Photo 38



Photo 39



Photo 41



Photo 43




Photo 45








Photo 44



Photo 46



Photo 47




Photo 49



Photo 51



Photo 53




Photo 48



Photo 50



Photo 52



Photo 54



Photo 55