

**LiveWest****REPAIRS TEAM**

**Issue** 30/05/2025  
**Priority** AP  
**Target** 27/06/2025 10:38

Occupier  
Scheme Long Ashton Road  
Long Ashton  
Bristol  
Somerset  
BS41 9HY

**Job Ref** UR0803664

**Client Ref** LW818905

**Preferred Job Contact:** 03001238080

**Access And Contact Information:****Appointment**

| Job Description   | Sun Code: | Date: | Time: |
|---|-----------|-------|-------|
|   | 500010    |       |       |
| Front wall damaged. Coping stone underneath iron railing has split off and bricks crumbling underneath . Porous brickwork, coping stone will need removing and replacing completely to ensure water tight and to prevent further damage/wall crumbling onto pavement below. |           |       |       |

**BE ASBESTOS AWARE**

- |                                     |          |  |          |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how?        |          |
| 3. What precautions are in place?   |          | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job?    | Yes / No | If no contact your Team Supervisor     |          |

**Property Attributes**

| Code     | Description                  | Status | Type   | Maint. Date |
|----------|------------------------------|--------|--------|-------------|
| SMOKMAIN | Smoke Detector - Mains Wired | Live   | DETECT |             |

**EXTRA WORK CARRIED OUT:**

Tradesman's Signature / Date

Please refer to our standard terms and conditions at [www.livewest.co.uk/terms-and-conditions/](http://www.livewest.co.uk/terms-and-conditions/)