

LiveWest

REPAIRS TEAM

Issue 19/05/2025
Priority AP
Target 16/06/2025 08:13

MS Fartuun Abdi Mohamuud
113 Lower Ashley Road
Easton
Bristol
BS5 0FH

Job Ref UR0796435

Client Ref LW812026

Preferred Job Contact: 07736782490

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
As Sales Force DMP002 Inspection - Lift slabs on first floor balcony at the rear to expose sub-surface so that cause of leak can be identified and resolved. Internal works will also be needed after leak repaired.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

Issue 19/05/2025
Priority AP
Target 16/06/2025 08:13

MS Fartuun Abdi Mohamuud
113 Lower Ashley Road
Easton
Bristol
BS5 0FH

Job Ref UR0796435

Client Ref LW812026

Preferred Job Contact: 07736782490

Property Attributes

Code	Description	Status	Type	Maint. Date
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	21-09-2026
CARCSN	CARCASS Pipework NG	Live	GAS	31-10-2025
UTILIT	UTILITY METER	Live	GAS	31-10-2025
FSTCKN	f/s cooker GT 60cm NG	Live	GAS	31-10-2025
CONCMN	CONDENSING COMBI BLR NG	Live	GAS	31-10-2025
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SPEAKING	Speaking or Talking			
COMMLANG	Communication Needs - Langua			

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date