LiveWest Issue 14/07/2025

ΑP **Priority REPAIRS TEAM**

> **Target** 11/08/2025 10:49

MISS Phillipa Smith Job Ref **UR0830892** 2 Bumblebee Close

Withywood LW847044

Client Ref Bristol

Preferred Job Contact: BS13 8BF

Access And Contact Information:

Sun Code: Date: Job Description 500010	Time:

Kitchen vinyl water damaged, burn holes and also missing under washing machine area. This should have been replaced at the void stage 1 month ago but left. Please replace 5m x 3m area.

BE ASBESTOS AWARE

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place? 4. Are any further precautions needed? Yes / No

5. Is it now safe to do the job? If no contact your Team Supervisor Yes / No

LiveWest Issue 14/07/2025

ΑP **Priority REPAIRS TEAM**

> Target 11/08/2025 10:49

MISS Phillipa Smith Job Ref UR0830892 2 Bumblebee Close

Withywood LW847044

Client Ref Bristol

Preferred Job Contact: BS13 8BF

Property Attributes

Code	Description	Status	Type	Maint. Date
CARCSN	CARCASS Pipework NG	Live	GAS	16-02-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	16-02-2026
EICR2	Electrical Installation Condition Report (EICR)	Live	EICR	10-02-2030
HARVEST	Rainwater harvesting	Live	RENEW	25-10-2025
MVHR	Mechanical Ventilation with Heat Recovery System	Live	RENEW	21-02-2026
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	16-02-2026
MOVING	Moving Around			

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/