LiveWest Issue 02/07/2025

REPAIRS TEAM Priority AP

Target 30/07/2025 15:47

MRS Stephanie Robinson

2 Grebe Road Job Ref UR0823305

Houndstone Client Ref LW840768

Yeovil Client Rei Lvvo407

Somerset **Preferred Job Contact:** 07814695878 BA22 8FY

Access And Contact Information:

Appointment

Sun Code: Date: Time:
500010

Repair the rear French door threshold sill as its loose and not packed correctly and letting in water .Cut back the slabs and fit a low profile ECO drain along the front edge of the French doors low level access sill and pack and fill internally to stop water ingress.

BE ASBESTOS AWARE

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place?

4. Are any further precautions needed?

Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor

LiveWest Issue 02/07/2025

REPAIRS TEAM Priority AP

Target 30/07/2025 15:47

MRS Stephanie Robinson

2 Grebe Road Job Ref UR0823305

Houndstone Yeovil Client Ref LW840768

Somerset Preferred Job Contact: 07814695878

BA22 8FY

Property Attributes

CARCEN	Description CARCASS Bingwork NC	Status	Type GAS	Maint. Date
CARCSN	CARCASS Pipework NG	Live	GAS	27-03-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
CONCMN	CONDENSING COMBI BLR NG	Live	GAS	27-03-2026
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	26-03-2030
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	27-03-2026
MOVING	Moving Around			

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/