

LiveWest

REPAIRS TEAM

Issue 06/03/2025
Priority AP
Target 03/04/2025 13:21

. Goldcroft Court Rethink
Flat 4 Goldcroft Court Goldcroft
Yeovil
Somerset
BA21 4DS

Job Ref UR0752236

Client Ref LW763460

Preferred Job Contact: 07918691365

Access And Contact Information:

ACCESS NOTES: Contact Agency CONTACT NOTES: Contact Agency

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Please arrange for contractor to replace timber window approx 630mmx1050mm. Window mech has failed and the window sash itself is spilt right down from the central gear box to the bottom. Hinges have also failed and are obsolete.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

Issue 06/03/2025
Priority AP
Target 03/04/2025 13:21

. Goldcroft Court Rethink
Flat 4 Goldcroft Court Goldcroft
Yeovil
Somerset
BA21 4DS

Job Ref **UR0752236**

Client Ref LW763460

Preferred Job Contact: 07918691365

Property Attributes

Code	Description	Status	Type	Maint. Date
UTILIT	UTILITY METER	Live	GAS	12-08-2025
CARCSN	CARCASS Pipework NG	Live	GAS	12-08-2025
EICR1	EICR LW 1 BEDROOM	Live	EICR1	09-10-2028
CONCMN	CONDENSING COMBI BLR NG	Live	GAS	12-08-2025
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date