LiveWest Issue 01/04/2025

REPAIRS TEAM Priority AP

Target 29/04/2025 13:17

MISS Victoria Jefferis
41 Aesop Drive

Job Ref UR0768911

Keynsham Client Ref LW780569

Bristol Evv7803

BS31 2GP Preferred Job Contact:

**Access And Contact Information:** 

Appointment

Sun Code: Date: Time:

500010

As Safety Culture RBS Inspection - Install low retaining wall along the side of the path and provide and guarding to address risk of slips and falls. Path approximately 14m long

## **BE ASBESTOS AWARE**

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place?

4. Are any further precautions needed?

Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor

LiveWest Issue 01/04/2025

ΑP **Priority REPAIRS TEAM** 

> Target 29/04/2025 13:17

MISS Victoria Jefferis Job Ref UR0768911 41 Aesop Drive

Keynsham LW780569 **Client Ref** 

Bristol

**Preferred Job Contact:** BS31 2GP

## **Property Attributes**

Code EICR1	Description Electrical Installation Condition Report (EICR)	<b>Status</b> Live	<b>Type</b> EICR	Maint. Date 23-06-2027
CARCSN	CARCASS Pipework NG	Live	GAS	07-02-2026
COMBLN	COMBI BOILER NG	Live	GAS	07-02-2026
UTILIT	UTILITY METER	Live	GAS	07-02-2026
FSTCKN	f/s cooker GT 60cm NG	Live	GAS	07-02-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
HEATMAIN	Heat Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
THINKING	Thinking or Feeling Clearly			

## **EXTRA WORK CARRIED OUT:**

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/