Room 9 - Window	#	Item	Description	Who?	Notes
	1	Restrictor	This needs to be unlocked to access all parts of the window.		
	2	Movement of	the pane on the top sash moves slightly/ is slightly insecure. This needs to be recured/	Sash Contractor	
		panes	resealed.		
	3	Top sash - Lower	The lower rail of the top sash is in poor condition. It will need to be sanded, filled, re-	Sash Contractor	
		Rail	sealed around window pains, redecorated.		
	4	Lower Sash -	The lower rail needs re-sealed and this section needs to be redecorated, sanded,	Sash Contractor	
		Lower rail	filled, primed, painted]		
	5	Redecoration	Both sash's should be painted after repairs completed.	Sash Contractor	