

LiveWest

REPAIRS TEAM

Issue 22/07/2025
Priority AP
Target 19/08/2025 16:18

MISS Kelsey McKenzie
2 Cable Close
Pucklechurch
Bristol
Gloucestershire
BS16 9AA

Job Ref UR0836554

Client Ref LW852647

Preferred Job Contact: 07306889339

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
As Sales Force RBS Inspection - Replace damaged window in lounge following fire, apply smoke stain block to window board, walls and ceiling and redecorate window board, walls and ceiling			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

Issue 22/07/2025
Priority AP
Target 19/08/2025 16:18

MISS Kelsey McKenzie
2 Cable Close
Pucklechurch
Bristol
Gloucestershire
BS16 9AA

Job Ref **UR0836554**

Client Ref LW852647

Preferred Job Contact: 07306889339

Property Attributes

Code	Description	Status	Type	Maint. Date
BLDINSLIVE	Building Insurance Live Case	Live	ALERT	
CARCSN	CARCASS Pipework NG	Live	GAS	11-02-2026
COBATT	CO Detector - Battery	Live	DETECT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	11-02-2026
EICR3	Electrical Installation Condition Report (EICR)	Live	EICR	06-08-2029
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	11-02-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date
