

LiveWest Repairs
Purchase Order

Page 1 of 3

Order No. CN011042

Date of order 08/07/2025

To:
BPM Contracting Services Ltd
12 Stable Yard
Bath
BA2 3AY

Delivery Address:
113 Lower Ashley Road
Easton
Bristol
BS5 0FH

Invoice Address:
LiveWest Homes Limited
1 Wellington Way
Skypark
Clyst Honiton
Exeter

Contact:
Charis Burton
Phone:
Fax:

Date due:

Job ID: UR0796435

Additional Instructions:

Code	Supplier	Description	Qty	Unit	VAT %	Unit Cost	Order Value

**LiveWest Repairs
Purchase Order**

Page 2 of 3

D20		<p>General - Ref Description Qty Total (Ex VAT)</p> <p>As Sales Force DMP002 Inspection - Lift slabs on first floor balcony at the rear to expose sub-surface so that cause of leak can be identified and resolved. Internal works will also be needed after leak repaired.</p> <p>1.00 0.0000</p> <p>1.00 0.0000</p> <p>007007 Flag:Lift any size existing precast concrete paving flag, fill and compact hardcore to soft spots and rebed existing flags on 25mm bed of cement mortar (1:4) and point up joints. SOR + quantity used to lift approx. 2sqm of concrete paving slabs from balcony, clean out any drainage gullies underneath and investigate cause of water ingress.</p> <p>4.00 96.4000</p> <p>413317 Ceiling:Take down existing ceiling, denail joists, fix ne 12.5mm plasterboard to ceiling in patch, scrim joints, 3mm skim plaster, additional battens, all labours, make good, remove waste and debris. SOR + quantity used to cut out and take down water damaged ceiling board and small section at head of window wall. Investigate cause of water ingress and renew plasterboard. Not allowed to re- plaster at this stage until leak is resolved.</p> <p>3.00 134.1600</p>	1.00	NO	20.00	230.56	230.56
-----	--	--	------	----	-------	--------	--------

**LiveWest Repairs
Purchase Order**

Page 3 of 3

Signed on behalf of LiveWest :	Nett Order Value	230.56
	VAT	46.11
	Gross Order Value	276.67

Please refer to our standard terms and conditions at <https://www.livewest.co.uk/about-us/tenders-and-suppliers>