

Invoice date: 24 Jun 2025

TO

GUINNESS PROPERTY

7th Floor, 350 Euston Roadd Regent's Place London, NW1 3AX

JOB ID #1410295

Job invoice ID: 991288 Service date: 3 Jun 2025

FROM

BPM CONTRACTING SERVICES LIMITED

12 Stable Yard, Windsor Bridge Road Bath, BA2 3AY VAT no. 934277606

JOB ADDRESS

31 Lumley Walk, Butterfield Down, Amesbury, Wiltshire, SP4

7SB

Property Ref: 11395

ITEM DESCRIPTION	VAT	NET AMOUNT
SHOWER:RENEW NE 8.5KW UNIT 830003 • Showers - Electric	£51.49 20%	£257.47
1 x £257.47		
Sub-total materials (excl. VAT)		£0.00
Sub-total labour (excl. VAT)		£257.47
Sub-total materials (incl. VAT)		£0.00
Sub-total labour (incl. VAT)		£308.96
	Total (excl. VAT)	£257.47
	Total VAT 20%	£51.49
	Total (incl. VAT)	£308.96

CIS deductions -Gross (0%)

-£0.00

Plentific

Toilet installation / repair

#1410295 Posted 3 Jun 2025, 10:21 by 31 Lumley Walk, Butterfield Down, Amesbury, Wiltshire, SP4 7SB

Account code: 490071 Plumbing DBS certification: Required

External reference (optional): 6113750/1

CIS DBS

APPOINTED

REF #6113750/1

Plumber & Toilet installation / repair

There is a LEAK FROM THE BACK SIDE OF THE TOILET. It is necessary to FIX THE LEAKING TOILET INLET VALVE, as the toilet is leaking.