

## LiveWest

### REPAIRS TEAM

**Issue** 02/07/2025  
**Priority** AP  
**Target** 30/07/2025 15:44

MRS Stephanie Robinson  
2 Grebe Road  
Houndstone  
Yeovil  
Somerset  
BA22 8FY

**Job Ref** UR0823303

**Client Ref** LW840766

**Preferred Job Contact:** 07814695878

#### Access And Contact Information:

#### Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Seal the existing latexed floor as water damage from old leak. Replace vinyl flooring 7.9mx 4m to the kitchen dinner area following damp and water damage .			

#### BE ASBESTOS AWARE

- |                                     |          |  |          |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how?        |          |
| 3. What precautions are in place?   |          | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job?    | Yes / No | If no contact your Team Supervisor     |          |

**Issue** 02/07/2025  
**Priority** AP  
**Target** 30/07/2025 15:44

MRS Stephanie Robinson  
2 Grebe Road  
Houndstone  
Yeovil  
Somerset  
BA22 8FY

**Job Ref** **UR0823303**

**Client Ref** LW840766

**Preferred Job Contact:** 07814695878

**Property Attributes**

Code	Description	Status	Type	Maint. Date
CARCSN	CARCASS Pipework NG	Live	GAS	27-03-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
CONCMN	CONDENSING COMBI BLR NG	Live	GAS	27-03-2026
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	26-03-2030
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	27-03-2026
MOVING	Moving Around			

**EXTRA WORK CARRIED OUT:**

<b>Tradesman's Signature / Date</b>
-------------------------------------