LiveWest		Issue	24/03/2025
REPAIRS TEAM		Priority	AP
		Target	21/04/2025 08:48
MS Rochiene O'Shea 2 School Mews Matson Gloucester Gloucestershire GL4 6BS	Preferred Job Contact:	Job Ref Client Ref 07376964018	<b>UR0763207</b> LW774605

## Access And Contact Information:

	Appointment		
Job Description	Sun Code: 500010	Date:	Time:
Daylight seen between wall and roof in loft. Customer experiencing damp and mould issues below. Please repair, could be defective lead. please see photos attached.			

## **BE ASBESTOS AWARE**

1. Have you identified the hazards?	Yes / No	2. Who might be harmed and how?	
3. What precautions are in place?		4. Are any further precautions needed?	Yes / No
5. Is it now safe to do the job?	Yes / No	If no contact your Team Supervisor	

LiveWest		Issue	24/03/2025
REPAIRS TEAM	Priority		AP
		Target	21/04/2025 08:48
MS Rochiene O'Shea 2 School Mews		Job Ref	UR0763207
Matson Gloucester		Client Ref	LW774605
Gloucestershire GL4 6BS	Preferred Job Contact:	07376964018	

BATHROOM BOXING UNKNOWN NO ASBESTOS BATHROOM CEILING TEXTURED COATING NO ASBESTOS BEDROOM 1 CEILING TEXTURED COATING NO ASBESTOS BEDROOM 2 CEILING TEXTURED COATING NO ASBESTOS CUPBOARD MISC CEILING TEXTURED COATING NO ASBESTOS CUPBOARD MISC CEILING TEXTURED COATING NO ASBESTOS EXTERNAL MISC CANOPY INSULATING BOARD NADIS EXTERNAL MISC PANELING INSULATING BOARD NADIS HALL CEILING TEXTURED COATING NADIS HALL FLOOR UNKNOWN NO ASBESTOS KITCHEN BOXING UNKNOWN NO ASBESTOS KITCHEN CEILING TEXTURED COATING NADIS KITCHEN CEILING TEXTURED COATING NADIS KITCHEN FLOOR VINYL FLOOR TILES NADIS LANDING CEILING TEXTURED COATING NADIS LOFT SPACE THROUGHOUT UNKNOWN NO ASBESTOS LOFT SPACE UNKNOWN LOCATION UNKNOWN NO ASBESTOS LOUNGE CEILING TEXTURED COATING NO ASBESTOS LOUNGE FLOOR UNKNOWN NO ASBESTOS ROOF UNDERCLOAK CEMENT FLAT SHEET CHRYSOTILE ROOF UNDERLINING BITUMEN COAT OR FELT NADIS STORE CANOPY INSULATING BOARD NO ASBESTOS UNDER STAIR CUPBOARD CEILING TEXTURED COATING NO ASBESTOS

LiveWest		Issue	24/03/2025
REPAIRS TEAM		Priority	AP
		Target	21/04/2025 08:48
MS Rochiene O'Shea 2 School Mews Matson Gloucester Gloucestershire GL4 6BS	Preferred Job Contact:	Job Ref Client Ref 07376964018	<b>UR0763207</b> LW774605

## **Property Attributes**

Code EICR2	Description Electrical Installation Condition Report (EICR)	<b>Status</b> Live	<b>Type</b> EICR	Maint. Date 12-08-2029
CARCSN	CARCASS Pipework NG	Live	GAS	28-08-2025
	I		-	
COMBLN	COMBI BOILER NG	Live	GAS	28-08-2025
UTILIT	UTILITY METER	Live	GAS	28-08-2025
ASBESCONF	Asbestos Confirmed (SQL)	Live	ALERT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
HEATMAIN	Heat Detector - Mains Wired	Live	DETECT	
THINKING	Thinking or Feeling Clearly			

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/