

LiveWest

REPAIRS TEAM

Issue 23/05/2025
Priority AP
Target 20/06/2025 16:32

MRS Katarzyna Soroczynska
20 Meadow Rise
Shepton Mallet
Somerset
BA4 5NS

Job Ref UR0800441

Client Ref LW816150

Preferred Job Contact: 07842165121

Access And Contact Information:

ACCESS NOTES: Contact Customer CONTACT NOTES: Contact Customer

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Erect Scaffold over the front porch to create a working platform to the front bedroom window above . Please let D2D know when put up, so we can carry out the window repairs.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

MRS Katarzyna Soroczynska
20 Meadow Rise
Shepton Mallet
Somerset
BA4 5NS

Job Ref **UR0800441**

Client Ref LW816150

Preferred Job Contact: 07842165121

BATHROOM ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BATHROOM ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BATHROOM CEILING TEXTURED COATING NADIS
BATHROOM CEILING TEXTURED COATING NO ASBESTOS
BEDROOM 1 ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BEDROOM 1 CEILING TEXTURED COATING NADIS
BEDROOM 2 ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BEDROOM 2 CEILING TEXTURED COATING NO ASBESTOS
BEDROOM 3 ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BEDROOM 3 CEILING TEXTURED COATING NADIS
BEDROOM 4 ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
BEDROOM 4 CEILING TEXTURED COATING NO ASBESTOS
CUPBOARD MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
CUPBOARD MISC CEILING TEXTURED COATING NO ASBESTOS
EXTERNAL MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
EXTERNAL MISC UNDERCLOAK CEMENT FLAT SHEET CROCIDOLITE
HALL ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
HALL CEILING TEXTURED COATING NADIS
KITCHEN ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
KITCHEN BOXING CEMENT FLAT SHEET NADIS
KITCHEN CEILING TEXTURED COATING NADIS
LANDING ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
LANDING CEILING TEXTURED COATING NADIS
LOBBY ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
LOBBY ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
LOBBY CEILING TEXTURED COATING NO ASBESTOS
LOBBY CEILING TEXTURED COATING NADIS
LOFT SPACE ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
LOFT SPACE ROOF BITUMEN COAT OR FELT NADIS
LOUNGE ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
LOUNGE CEILING TEXTURED COATING NADIS
PORCH ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
PORCH CEILING CEMENT FLAT SHEET NO ASBESTOS
STORE ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
STORE CEILING CEMENT FLAT SHEET NADIS
UNDER STAIR CUPBOARD ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
UNDER STAIR CUPBOARD CEILING TEXTURED COATING NO ASBESTOS
WATER TANK CUPBOARD ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
WATER TANK CUPBOARD CEILING TEXTURED COATING NO ASBESTOS
WC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

Issue 23/05/2025
Priority AP
Target 20/06/2025 16:32

MRS Katarzyna Soroczynska
20 Meadow Rise
Shepton Mallet
Somerset
BA4 5NS

Job Ref UR0800441

Client Ref LW816150

Preferred Job Contact: 07842165121

WC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
WC BOXING CEMENT FLAT SHEET NADIS
WC CEILING TEXTURED COATING NO ASBESTOS
WC CEILING TEXTURED COATING NADIS
WC FLOOR VINYL FLOOR TILES NADIS

Property Attributes

Code	Description	Status	Type	Maint. Date
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	09-07-2028
CARCSN	CARCASS Pipework NG	Live	GAS	05-11-2025
UTILIT	UTILITY METER	Live	GAS	05-11-2025
FSTCKN	f/s cooker GT 60cm NG	Live	GAS	05-11-2025
ASBESPRES	Asbestos Presumed (SQL)	Live	ALERT	
CONSYN	CONDENSING SYS BLR NG	Live	GAS	05-11-2025
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
COMMLANG	Communication Needs - Langua			
COMMLANG	Communication Needs - Langua			

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date