



S N SCAFFOLDS LLP

report prepared for

BPM MAINTENANCE

SCAFFOLD INSPECTION REPORT

All in accordance with the work at height regulations 2005 Schedule 7

Report Type:

Inspection Summary

Contract Number:

0001

Site Name:




1-14 Griffin Court

Site Address:

Bath

Date:

9th December 2024 - 10th December 2024

Scaffold	Name	Area	Inspection Type	Result	Identified risks to the health and safety of any person	Hazards reported to	Inspector's recommendations	Inspector	Date & time
	00001-DN1	1-14 Griffin Court	 Strong Winds	N	All good at time of inspection and signing of tag	None	None	S L Noad (Scaffold Inspector) 	09/12/24 10:20

Appendix



0001-DN1:Inspection Photo (09/12/24 10:20)



0001-DN1:Inspection Photo (09/12/24 10:20)



0001-DN1:Inspection Photo (09/12/24 10:20)



0001-DN1:Inspection Photo (09/12/24 10:20)