



S N SCAFFOLDS LLP

report prepared for

BPM MAINTENANCE

SCAFFOLD INSPECTION REPORT

All in accordance with the work at height regulations 2005 Schedule 7

Report Type:

Inspection Summary

Contract Number:

0001

Site Name:



16 Blackhorse Court

Site Address:

Bristol

Date:

24th July 2025 - 25th July 2025

Scaffold	Name	Area	Inspection Type	Result	Identified risks to the health and safety of any person	Hazards reported to	Inspector's recommendations	Inspector	Date & time	
	00001-DN1	16 Blackhorse Court	Default area	7	N	All scaffold on site appears to be safe and secure at the time of inspection	None	None	Dom Noad (Contract Manager) 	24/07/25 10:25

Appendix



00001-DN1:Inspection Photo (24/07/25 10:25)



00001-DN1:Inspection Photo (24/07/25 10:25)