



S N SCAFFOLDS LLP

report prepared for

BPM MAINTENANCE

SCAFFOLD INSPECTION REPORT

All in accordance with the work at height regulations 2005 Schedule 7

Report Type:

Inspection Summary

Contract Number:

0001

Site Name:



33 Corn Street

Site Address:

Bath

Date:

28th July 2025 - 29th July 2025

Scaffold	Name	Area	Inspection Type	Result	Identified risks to the health and safety of any person	Hazards reported to	Inspector's recommendations	Inspector	Date & time	
	00001-DN1	33 Corn Street		7	N	All scaffold on site appears to be safe and secure at the time of inspection	None	None	Dom Noad (Contract Manager) 	28/07/25 10:41

Appendix



00001-DN1:Inspection Photo (28/07/25 10:41)



00001-DN1:Inspection Photo (28/07/25 10:41)