



S N SCAFFOLDS LLP

report prepared for

BPM MAINTENANCE

---

## SCAFFOLD INSPECTION REPORT

---

All in accordance with the work at height regulations 2005 Schedule 7

**Report Type:**

Inspection Summary

**Contract Number:**

0001

**Site Name:**



22 Horne Close

**Site Address:**

Stratton-on-the-Fosse

**Date:**

29th July 2025 - 30th July 2025

| Scaffold  | Name      | Area           | Inspection Type | Result | Identified risks to the health and safety of any person | Hazards reported to  | Inspector's recommendations | Inspector | Date & time   |                   |
|---|-----------|----------------|-----------------|--------|---|--|-----------------------------|-----------|---|-------------------|
|  | 00001-DN1 | 22 Horne Close | Default area    | 7      | N   | All scaffold on site appears to be safe and secure at the time of inspection | None                        | None      | Dom Noad<br>(Contract Manager)<br> | 29/07/25<br>11:17 |

## Appendix



00001-DN1:Inspection Photo (29/07/25 11:17)



00001-DN1:Inspection Photo (29/07/25 11:17)



00001-DN1:Inspection Photo (29/07/25 11:17)



00001-DN1:Inspection Photo (29/07/25 11:17)