

LiveWest

REPAIRS TEAM

Issue 02/07/2025
Priority AP
Target 30/07/2025 12:03

MISS Natasha Ferson
21 Forth Avenue
Portishead
Bristol
Somerset
BS20 7NQ

Job Ref UR0823106

Client Ref LW840549

Preferred Job Contact: 07498757580

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Footpath heading to 21 Forth Avenue has 26 slabs that are uneven, rocking, and damaged which need to be replaced and 8 slabs joining along the same path leading to properties 19-17 to be replaced.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

Issue 02/07/2025
Priority AP
Target 30/07/2025 12:03

MISS Natasha Ferson
21 Forth Avenue
Portishead
Bristol
Somerset
BS20 7NQ

Job Ref **UR0823106**

Client Ref LW840549

Preferred Job Contact: 07498757580

Property Attributes

Code	Description	Status	Type	Maint. Date
CARCSN	CARCASS Pipework NG	Live	GAS	14-05-2026
COBATT	CO Detector - Battery	Live	DETECT	
COBATT	CO Detector - Battery	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	14-05-2026
EICR2	Electrical Installation Condition Report (EICR)	Live	EICR	09-04-2029
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	14-05-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date
