

LiveWest

REPAIRS TEAM

Issue 16/04/2025
Priority AP
Target 14/05/2025 14:31

MRS Sharon Sully
43 Fulford Road
Hartcliffe
Bristol
BS13 9RL

Job Ref UR0778325

Client Ref LW791639

Preferred Job Contact: 07583704489

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Wooden corner post supporting the front porch is very rotten and needs replacing . Temporary Acro prop installed by D2D until works are complete. Pictures and scope sent to Specialist.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

Issue 16/04/2025
Priority AP
Target 14/05/2025 14:31

MRS Sharon Sully
43 Fulford Road
Hartcliffe
Bristol
BS13 9RL

Job Ref **UR0778325**

Client Ref LW791639

Preferred Job Contact: 07583704489

Property Attributes

Code	Description	Status	Type	Maint. Date
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	30-04-2026
CARCSN	CARCASS Pipework NG	Live	GAS	10-02-2026
COMBLN	COMBI BOILER NG	Live	GAS	10-02-2026
UTILIT	UTILITY METER	Live	GAS	10-02-2026
BINHBN	built-in hob NG	Live	GAS	10-02-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
HEATMAIN	Heat Detector - Mains Wired	Live	DETECT	

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/