LiveWest Issue 11/07/2025

REPAIRS TEAM Priority AP

Target 08/08/2025 11:19

MISS Mary Friend
43 Sidford Road

Job Ref UR0830154

Bedminster
Bristol

Client Ref LW846152

Bristol Preferred Job Contact: 07716888722

BS3 5DN

Access And Contact Information:

		Appointment			
Job Description	Sun Code: 500010	Date:	Time:		
·					

ROOFER TO ATTEND TO UNBLOCK TILE VENT AND REMOVE FLY SCREEN. PLEASE CHECK BOTH VENTS AS RIGHT NEXT TO EACH OTHER

BE ASBESTOS AWARE

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place?

4. Are any further precautions needed?

Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor

LiveWest Issue 11/07/2025

REPAIRS TEAM Priority AP

Target 08/08/2025 11:19

MISS Mary Friend
43 Sidford Road

Job Ref UR0830154

Bedminster Client Ref LW846152

Bristol

Bristol Preferred Job Contact: 07716888722

BS3 5DN

Property Attributes

Code CARCSN	Description CARCASS Pipework NG	Status Live	Type GAS	Maint. Date 09-04-2026
COBATT	CO Detector - Battery	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	09-04-2026
EICR2	Electrical Installation Condition Report (EICR)	Live	EICR	20-05-2029
HCMAIN	Heat and CO Detector - Mains Wired	Live	DETECT	
MVHR	Mechanical Ventilation with Heat Recovery System	Live	RENEW	29-01-2026
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	09-04-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/