

LiveWest

REPAIRS TEAM

Issue 16/06/2025
Priority AP
Target 14/07/2025 16:03

MISS Donna Thomas
45 Fulford Road
Hartcliffe
Bristol
BS13 9RL

Job Ref UR0813894

Client Ref LW830426

Preferred Job Contact: 07522816649

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Wooden corner post supporting the front porch is very rotten and needs replacing . Approx. 4" x 4" x 2m.			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

LiveWest

REPAIRS TEAM

Issue 16/06/2025
Priority AP
Target 14/07/2025 16:03

MISS Donna Thomas
45 Fulford Road
Hartcliffe
Bristol
BS13 9RL

Job Ref UR0813894

Client Ref LW830426

Preferred Job Contact: 07522816649

Property Attributes

Code	Description	Status	Type	Maint. Date
CARCSN	CARCASS Pipework NG	Live	GAS	22-04-2026
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	22-04-2026
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	17-07-2028
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	22-04-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/