

**LiveWest**

**REPAIRS TEAM**

**Issue** 28/02/2025  
**Priority** AP  
**Target** 28/03/2025 08:33

MR Stuart Hawker  
53 Ecos Court  
Frome  
Somerset  
BA11 1HY

**Job Ref** **UR0747534**

**Client Ref** LW758550

**Preferred Job Contact:** 07598505373

**Access And Contact Information:**

ACCESS NOTES: Contact Customer CONTACT NOTES: Contact Customer

**Appointment**

Job Description	Sun Code:	Date:	Time:
	500010		
Section of stone has come away and broken from the side of the front door. Its needs a stone Mason to cut a new piece and fit. Property is listed and Photos sent over.			

**BE ASBESTOS AWARE**

- |                                     |          |  |          |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how?        |          |
| 3. What precautions are in place?   |          | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job?    | Yes / No | If no contact your Team Supervisor     |          |

AIRING CUPBOARD CEILING TEXTURED COATING NO ASBESTOS  
BATHROOM CEILING VISUALLY NO SUSPECT NO ASBESTOS  
BATHROOM WALL VISUALLY NO SUSPECT NO ASBESTOS  
BEDROOM 1 CEILING TEXTURED COATING NADIS  
BEDROOM 2 CEILING INSULATING BOARD NADIS  
BEDROOM 2 WALL INSULATING BOARD NADIS  
EXTERNAL MISC UNDERCLOAK CEMENT FLAT SHEET CROCIDOLITE  
EXTERNAL MISC UNKNOWN LOCATION UNKNOWN NO ASBESTOS  
HALL CEILING TEXTURED COATING NADIS  
KITCHEN CEILING TEXTURED COATING NADIS  
KITCHEN WALL INSULATING BOARD NADIS  
LANDING CEILING TEXTURED COATING NO ASBESTOS  
LOFT SPACE CEILING INSULATING BOARD NADIS  
LOFT SPACE UNKNOWN LOCATION UNKNOWN NO ASBESTOS  
LOUNGE CEILING TEXTURED COATING NADIS  
LOUNGE WALL VISUALLY NO SUSPECT NO ASBESTOS  
UNDER STAIR CUPBOARD CEILING TEXTURED COATING NADIS  
UNDER STAIR CUPBOARD WALL INSULATING BOARD NADIS

**Issue** 28/02/2025  
**Priority** AP  
**Target** 28/03/2025 08:33

MR Stuart Hawker  
53 Ecos Court  
Frome  
Somerset  
BA11 1HY

**Job Ref** UR0747534

**Client Ref** LW758550

**Preferred Job Contact:** 07598505373

#### Property Attributes

Code	Description	Status	Type	Maint. Date
EICR2	EICR LW 2 BEDROOM	Live	EICR2	10-09-2028
COMBLN	COMBI BOILER NG	Live	GAS	16-05-2025
UTILIT	UTILITY METER	Live	GAS	16-05-2025
CARCSN	CARCASS Pipework NG	Live	GAS	16-05-2025
ASBESPRES	Asbestos Presumed (SQL)	Live	ALERT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
THINKING	Thinking or Feeling Clearly			

---

#### EXTRA WORK CARRIED OUT:

<b>Tradesman's Signature / Date</b>
-------------------------------------