LiveWest Issue 28/03/2025

ΑP **Priority REPAIRS TEAM** 

> Target 25/04/2025 08:49

MISS Sarah-Jane Lewis

56 Brue Close

BS23 3BX

Job Ref UR0766921

07340518993

Weston-super-Mare LW778176 **Client Ref** 

**Preferred Job Contact:** 

Somerset

**Access And Contact Information:** 

		Appointment			
	Sun Code:	Date:	Time:		
Job Description	500010				
holes in the roofing felt_daylig	tht can been seen threw the roof				

## **BE ASBESTOS AWARE**

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place? 4. Are any further precautions needed? Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor LiveWest Issue 28/03/2025

REPAIRS TEAM Priority AP

Target 25/04/2025 08:49

MISS Sarah-Jane Lewis

Job Ref UR0766921

56 Brue Close Job Rei UR076692

Weston-super-Mare Client Ref LW778176

BS23 3BX Preferred Job Contact: 07340518993

BATHROOM ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

BATHROOM CEILING TEXTURED COATING NADIS

BEDROOM 1 CEILING TEXTURED COATING NO ASBESTOS

BEDROOM 2 CEILING TEXTURED COATING NO ASBESTOS

BEDROOM 3 CEILING TEXTURED COATING NO ASBESTOS

BEDROOM 4 CEILING TEXTURED COATING NO ASBESTOS

EXTERNAL MISC THROUGHOUT UNKNOWN NO ASBESTOS

HALL CEILING TEXTURED COATING NO ASBESTOS

KITCHEN BOXING UNKNOWN NO ASBESTOS

KITCHEN BOXING VISUALLY NO SUSPECT NO ASBESTOS

KITCHEN BOXING VISUALLY NO SUSPECT NO ASBESTOS

KITCHEN CEILING TEXTURED COATING NADIS

KITCHEN SINK PAD BITUMEN PAD ON SINK NADIS

LANDING CEILING TEXTURED COATING NADIS

LANDING CEILING TEXTURED COATING NADIS

LOFT SPACE THROUGHOUT UNKNOWN NO ASBESTOS

LOUNGE CEILING TEXTURED COATING NO ASBESTOS

STORE CEILING TEXTURED COATING NO ASBESTOS

WATER TANK CUPBOARD CEILING TEXTURED COATING NO ASBESTOS

WC BOXING UNKNOWN NO ASBESTOS

WC BOXING VISUALLY NO SUSPECT NO ASBESTOS

WC BOXING VISUALLY NO SUSPECT NO ASBESTOS

WC CEILING TEXTURED COATING NADIS

WC CEILING TEXTURED COATING NADIS

WC WALL VISUALLY NO SUSPECT NO ASBESTOS

LiveWest Issue 28/03/2025

REPAIRS TEAM Priority AP

Target 25/04/2025 08:49

MISS Sarah-Jane Lewis

56 Brue Close Job Ref UR0766921

Weston-super-Mare
Somerset

Client Ref LW778176

BS23 3BX Preferred Job Contact: 07340518993

## **Property Attributes**

Description Electrical Installation Condition Report (EICR)	<b>Status</b> Live	<b>Type</b> EICR	Maint. Date 04-03-2028
CARCASS Pipework NG	Live	GAS	09-09-2025
UTILITY METER	Live	GAS	09-09-2025
Presumed Asbestos Free (SQL)	Live	ALERT	
CONDENSING SYS BLR NG	Live	GAS	09-09-2025
CO Detector - Battery	Live	DETECT	
Smoke Detector - Mains Wired	Live	DETECT	
Smoke Detector - Mains Wired	Live	DETECT	
Holding or Grasping			
Moving Around			
	Electrical Installation Condition Report (EICR) CARCASS Pipework NG UTILITY METER Presumed Asbestos Free (SQL) CONDENSING SYS BLR NG CO Detector - Battery Smoke Detector - Mains Wired Smoke Detector - Mains Wired Holding or Grasping	Electrical Installation Condition Report (EICR)  CARCASS Pipework NG  Live  UTILITY METER  Presumed Asbestos Free (SQL)  CONDENSING SYS BLR NG  CO Detector - Battery  Smoke Detector - Mains Wired  Holding or Grasping	Electrical Installation Condition Report (EICR)  CARCASS Pipework NG  Live  GAS  UTILITY METER  Live  GAS  Presumed Asbestos Free (SQL)  CONDENSING SYS BLR NG  CO Detector - Battery  Smoke Detector - Mains Wired  Holding or Grasping

## **EXTRA WORK CARRIED OUT:**

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/