

Issue 20/06/2025
 Priority AP
 Target 18/07/2025 11:31

MS Annemarie Bellinger
 8 Hanover Place
 Bristol
 Bristol
 BS1 6XT

Job Ref **UR0816797**

Client Ref LW833019

Preferred Job Contact: 07718064314

Access And Contact Information:

Appointment

Job Description	Sun Code:	Date:	Time:
	500010		
Cracking to render under archway carefully hack back the cracked area 5 sq mtrs approx prepare substrate with bonding agent and re render area once completed remove all debris and leave site clean and tidy			

BE ASBESTOS AWARE

- | | | | |
|-------------------------------------|----------|--|----------|
| 1. Have you identified the hazards? | Yes / No | 2. Who might be harmed and how? | |
| 3. What precautions are in place? | | 4. Are any further precautions needed? | Yes / No |
| 5. Is it now safe to do the job? | Yes / No | If no contact your Team Supervisor | |

BATHROOM THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 BEDROOM 1 THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 BEDROOM 2 THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 BEDROOM 3 THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 BEDROOM 4 THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 CYLINDER CUPBOARD THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 EXTERNAL MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
 EXTERNAL MISC UNDERCLOAK CEMENT FLAT SHEET CHRYSOTILE
 HALL THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 KITCHEN ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS
 KITCHEN SINK PAD BITUMEN PAD ON SINK NADIS
 LANDING THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 LOFT SPACE THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 LOFT SPACE THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 LOUNGE THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 UNDER STAIR CUPBOARD THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 WC THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS
 WC THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS

Issue 20/06/2025
Priority AP
Target 18/07/2025 11:31

MS Annemarie Bellinger
8 Hanover Place
Bristol
Bristol
BS1 6XT

Job Ref **UR0816797**

Client Ref LW833019

Preferred Job Contact: 07718064314

Property Attributes

Code	Description	Status	Type	Maint. Date
ASBESCONF	Asbestos Confirmed (SQL)	Live	ALERT	
CARCSN	CARCASS Pipework NG	Live	GAS	19-12-2025
COMAIN	CO Detector - Mains Wired	Live	DETECT	
COMBLN	COMBI BOILER NG	Live	GAS	19-12-2025
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	16-04-2029
FSTCKN	f/s cooker GT 60cm NG	Live	GAS	19-12-2025
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	19-12-2025

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/