LiveWest Issue 31/01/2025

ΑP **Priority REPAIRS TEAM** 

> Target 28/02/2025 09:12

MS Kennedy Bonner 80 Puttingthorpe Drive

Job Ref UR0726584

Weston-super-Mare

LW737890 **Client Ref** 

Somerset

**Preferred Job Contact:** 07903409969 **BS22 8LG** 

**Access And Contact Information:** 

		Appointment			
Job Description	<b>Sun Code:</b> 500010	Date:	Time:		
Roof tile fallen onto the drivew	ay in the strong winds	·	·		

## **BE ASBESTOS AWARE**

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place? 4. Are any further precautions needed? Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor LiveWest Issue 31/01/2025

**Priority** ΑP **REPAIRS TEAM** 

> Target 28/02/2025 09:12

MS Kennedy Bonner Job Ref UR0726584 80 Puttingthorpe Drive

Weston-super-Mare LW737890 **Client Ref** 

Somerset

**Preferred Job Contact:** 07903409969 **BS22 8LG** 

## **Property Attributes**

Code EICR4	Description EICR LW 4 BEDROOM	<b>Status</b> Live	<b>Type</b> EICR4	Maint. Date 30-05-2029
CARCSN	CARCASS Pipework NG	Live	GAS	05-09-2025
COMBLN	COMBI BOILER NG	Live	GAS	05-09-2025
UTILIT	UTILITY METER	Live	GAS	05-09-2025
ASBESPRES	Asbestos Presumed (SQL)	Live	ALERT	
COMAIN	CO Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	

## **EXTRA WORK CARRIED OUT:**

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/