LiveWest Issue 25/06/2025

ΑP **Priority REPAIRS TEAM**

> **Target** 23/07/2025 16:38

> > **UR0820022**

Job Ref

Occupier

Block 2-6 Exchange Court

Hanham Road **Client Ref**

LW836009 Bristol

Preferred Job Contact: 03001238080 Gloucestershire

BS15 8PL

Access And Contact Information:

		Appointment			
Job Description	Sun Code : 500010	Date:	Time:		

Timber window located in the communal stairwell is rotten beyond repair and will need replacing with white uPVC. Located on the 2nd floor. Window size 930mmx600mm fixed light (non opening)with trickle vent and 150mm cill included in size. Contractors to erect external scaffolding but will need permission from BT, or complete internal replacement with stair scaffolding.

BE ASBESTOS AWARE

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place? 4. Are any further precautions needed? Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor LiveWest Issue 25/06/2025

REPAIRS TEAM Priority AP

Target 23/07/2025 16:38

Occupier

Block 2-6 Exchange Court

Job Ref UR0820022

Hanham Road

Rristol Client Ref LW836009

Gloucestershire Preferred Job Contact: 03001238080

BS15 8PI

BATHROOM ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

BATHROOM BOXING VISUALLY NO SUSPECT NO ASBESTOS

BATHROOM CEILING TEXTURED COATING NADIS

BATHROOM CEILING TEXTURED COATING NO ASBESTOS

BATHROOM WALL VISUALLY NO SUSPECT NO ASBESTOS

BEDROOM CEILING TEXTURED COATING NO ASBESTOS

BEDROOM 1 CEILING TEXTURED COATING NO ASBESTOS

BEDROOM 2 CEILING TEXTURED COATING NO ASBESTOS BEDROOM 2 CEILING TEXTURED COATING NO ASBESTOS

CUPBOARD MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

CUPBOARD MISC CEILING TEXTURED COATING NO ASBESTOS

CUPBOARD MISC CEILING TEXTURED COATING NADIS

CUPBOARD MISC WALL VISUALLY NO SUSPECT NO ASBESTOS

ELECTRICAL CUPBOARD THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS

EXTERNAL MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

EXTERNAL MISC UNDERCLOAK CEMENT FLAT SHEET NADIS

HALL ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

HALL CEILING TEXTURED COATING NADIS

HALL THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS

KITCHEN ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

KITCHEN CEILING TEXTURED COATING NADIS

KITCHEN LINING INSULATING BOARD NADIS

KITCHEN SINK PAD BITUMEN PAD ON SINK NADIS

LANDING BOXING VISUALLY NO SUSPECT NO ASBESTOS

LANDING CEILING TEXTURED COATING NO ASBESTOS

LANDING THROUGHOUT UNKNOWN NO ASBESTOS

LANDING THROUGHOUT UNKNOWN NO ASBESTOS

LANDING THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS

LANDING THROUGHOUT VISUALLY NO SUSPECT NO ASBESTOS

LOUNGE ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

LOUNGE BOXING VISUALLY NO SUSPECT NO ASBESTOS

LOUNGE CEILING TEXTURED COATING NO ASBESTOS

LOUNGE CEILING TEXTURED COATING NADIS

LOUNGE WALL VISUALLY NO SUSPECT NO ASBESTOS

OFFICE ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

OFFICE CEILING TEXTURED COATING NO ASBESTOS

OFFICE CEILING TEXTURED COATING NADIS

OFFICE SINK PAD BITUMEN PAD ON SINK NADIS

OFFICE WALL VISUALLY NO SUSPECT NO ASBESTOS

ROOF ROOF VISUALLY NO SUSPECT NO ASBESTOS

LiveWest Issue 25/06/2025

ΑP **Priority REPAIRS TEAM**

> **Target** 23/07/2025 16:38

Occupier

UR0820022 Job Ref Block 2-6 Exchange Court

Hanham Road LW836009 **Client Ref**

Bristol

Preferred Job Contact: 03001238080 Gloucestershire

BS15 8PL

Property Attributes

Code AOVMAINT	Description Automatic Opening Vents	Status Live	Type CFS	Maint. Date 19-11-2025
ASBESFREE	Presumed Asbestos Free (SQL)	Live	ALERT	10-11-2020
CARCSN	CARCASS Pipework NG	Live	GAS	02-06-2026
COBATT	CO Detector - Battery	Live	DETECT	
COMM FRDRS	COMMUNAL FIRE DOORS - 4	Live	FIREDR12M	19-05-2026
CONCMN	CONDENSING COMBI BLR NG	Live	GAS	02-06-2026
EICR4	Electrical Installation Condition Report (EICR)	Live	EICR	17-08-2027
EMERLIGHT	12mth Servicing of Emergency Lighting	Live	CFS12	19-11-2025
FDAS-MEDIUM Fire Detection Alarm System - Medium		Live	CFS	19-11-2025
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
SMOKMAIN	Smoke Detector - Mains Wired	Live	DETECT	
UTILIT	UTILITY METER	Live	GAS	02-06-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/