LiveWest Issue 28/07/2025

REPAIRS TEAM Priority AP

Target 25/08/2025 14:52

MISS Fern Whittaker

Flat 2 Curlew House 2 Harbour

Job Ref UR0839816

Close
Bristol

Client Ref LW855507

Bristol Preferred Job Contact: 07359488104

BS11 9FT

## **Access And Contact Information:**

Sun Code: Date: Time: 500010		 Appointment				
	Job Description	Date:	Time:			

Following Sales Force RBS Inspection - Lift vinyl sheet flooring in kitchen area and bathroom to allow inspection of screed below for possible leaks. Joint Inspection with RBS to be co-ordinated.

## **BE ASBESTOS AWARE**

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place?

4. Are any further precautions needed?

Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor

LiveWest Issue 28/07/2025

REPAIRS TEAM Priority AP

Target 25/08/2025 14:52

MISS Fern Whittaker

Flat 2 Curlew House 2 Harbour

Job Ref UR0839816

Close
Bristol

Client Ref LW855507

Bristol Preferred Job Contact: 07359488104

BS11 9FT

## **Property Attributes**

Code	Description	Status	Type	Maint. Date
ASHP	Air Source Heat Pump	Live	RENEW	30-07-2025
EICR2	Electrical Installation Condition Report (EICR)	Live	EICR	27-07-2029
FRDR DWLLNG FIRE DOOR - DWELLING		Live	FIREDR24M	21-11-2026
RENEWOVER	Renewable Tech Safety Check Due - CONFIRM APPT	Live	ALERT	
SOLARPV	Solar PV	Live	EICR	27-07-2029

## **EXTRA WORK CARRIED OUT:**

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/