

IMS - Advanced Component Replacement request form V1

Flat 16, Blackhorse Court, Blackhorse Road, Kingswood, Bristol, BS15 8EA

Complete

Score	6 / 6 (100%)	Flagged items	0	Actions	0
ACR Requested	d By:			Julian Mallia - RBS North, I North - Martin Daymo Surveying & Compliand Matthew Messenger, North RE Laura Mi	nd, ce - 3S -
Customer Nan	ne:			Miss Tiffany Park 07809 473	103
Customer Add	ress:			Flat 16, Blackhorse Cou Blackhorse Road, Kingswo Bristol, BS15 8	od,

Untitled Page	6 / 6 (100%)		
Component requiring replacement:	Windows		
Keystone review date:	1 Apr 2030		
Keystone Replacement Cost:	NK		
Number of previous repair attempts:	0		
Relating job numbers:			
Unknown if repairs have been attempted			
Please tick all relevant options below:	5 / 5 (100%)		
Health and safety concern	No		
Works relate to a complaint	No		
Works relate to a disrepair case	No		
HHSRS	No		
Works relate to a compliance issue	No		
Information	1 / 1 (100%)		
Can a mitigatory repair be utilised to see the component into the next financial year? Please provide details	No		
Casements and frames in this flat are rotten and the windows span two storeys as a single frame with opening lights.			
	A TOTAL CONTRACTOR OF THE STATE		

Please select appropriate Red/ Amber/ Green status for this request:

Amber - mitigatory repairs have taken place but these are not long lasting and the component must be replaced next financial year.

Any other relevant information to support the request:

The south facing windows are in a worse condition than other windows. Suspect that the property may be listed. The windows are timber framed.

Evidence:

Clear photos demonstrating the need for the component replacement must be provided with this form.

1.Photo



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16

2.	Ρ	h	0	to
			v	CO

3.Photo

4.Photo

6.Photo

7.Photo

Media summary



Photo 1



Photo 3



Photo 2



Photo 4



Photo 5



Photo 7



Photo 9



Photo 6



Photo 8



Photo 10



Photo 11



Photo 13



Photo 15



Photo 12



Photo 14



Photo 16