LiveWest 18/06/2025 Issue

ΑP **Priority REPAIRS TEAM**

> Target 16/07/2025 14:53

> > **UR0814986**

LW831703

Occupier

Block 16-19 Blackhorse Court

Access And Contact Information:

Blackhorse Road

Kingswood Bristol

Gloucestershire

BS15 8EA

Preferred Job Contact:

Appointment

Job Ref

Client Ref

Sun Code: Time: Date: 500010 Job Description

Roofing works - leak identified on roof while completing works to the kitchen (UR0745866)

BE ASBESTOS AWARE

1. Have you identified the hazards? Yes / No 2. Who might be harmed and how?

3. What precautions are in place? 4. Are any further precautions needed? Yes / No

5. Is it now safe to do the job? Yes / No If no contact your Team Supervisor

CANOPY ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

CANOPY ROOF TILES CEMENT FLAT SHEET NO ASBESTOS

EXTENSION ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

EXTENSION ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

EXTENSION ROOF TILES CEMENT FLAT SHEET NO ASBESTOS

EXTENSION ROOF TILES CEMENT FLAT SHEET NADIS

EXTERNAL MISC ALL OTHER ELEMENTS VISUALLY NO SUSPECT NO ASBESTOS

EXTERNAL MISC ROOF TILES CEMENT FLAT SHEET CROCIDOLITE

EXTERNAL MISC SOFFIT INSULATING BOARD CROCIDOLITE

LiveWest Issue 18/06/2025

REPAIRS TEAM Priority AP

Target 16/07/2025 14:53

UR0814986

Job Ref

Occupier

Block 16-19 Blackhorse Court

Blackhorse Road Client Ref LW831703

Kingswood

Gloucestershire BS15 8EA

Bristol

Preferred Job Contact:

Property Attributes

CodeDescriptionStatusTypeMaint. DateASBESPRESAsbestos Presumed (SQL)LiveALERTEICR4Electrical Installation Condition Report (EICR)LiveEICR03-06-2026

EXTRA WORK CARRIED OUT:

Tradesman's Signature / Date

Please refer to our standard terms and conditions at www.livewest.co.uk/terms-and-conditions/