

Completion report

Job title	Decorative cornicing / plasterwork
Job posted by	Eloise Lawrence
Location address	4F New King Street, Bath, BA1 2BL, GB, Avon
Submitted 09/04/2025 16:00, by Abbins Maintenance Abbins Maintenance Limited	Signed off at 21/04/2025 14:06 by Tomasz Sendra Guinness Property

Job outcome

Outcome of the job

FULLY_COMPLETED

On-site work completed date and time

20/03/2025 00:00

Detailed description of the work

Good Afternoon,

Our operative attended the property and carried out a drone inspection of the roof, he reported back the following;

- There is usually a lot going on with roofs that have a gully/parapet wall like this roof,
- We couldn't pinpoint and exact issue and would require inspection scaffolding to get up and assess the roof properly.

Unfortunately as this would require scaffolding, it would surpass the deadline date.

We will invoice this one for a drone survey and attendance.





Kind regards,

Jack

Abbins Maintenance Ltd

Job documentation

Media and/or documents of the work completed



Additional work or issues

Are there any additional work or issues identified?

No